



①	Switching setpoint 1 / setpoint 2	Umschaltung Sollwert 1 / Sollwert 2
②	Pressure connections	Druckanschlüsse
③	Voltage supply 10...24V DC	Spannungsversorgung 10...24V DC
④	Output 0...10V	Ausgang 0...10V

	L1	Power supply, phase, 50/60 Hz	Versorgungsspannung, Phase, 50/60 Hz
	N	Neutral conductor	Neutralleiter
	PE	Ground connection, PE connection	Erdanschluss, PE Anschluss
	0-10V / PWM	0-10V / PWM control input, Ri=100kOhm, SELV	0-10V / PWM Steuereingang, Ri=100kOhm, SELV
	Tacho	Tacho output, open collector, 1 pulse per revolution, Isink max = 10mA, SELV	Drehzahlüberwachungsausgang, open collector, 1 Impuls pro Umdrehung, Isink max = 10mA, SELV
	+10V	Fixed voltage output 10 VDC, +10 V ±3%; max. 10 mA; short-circuit-proof; power supply forexternal devices (e.g. pot)	Festspannungsausgang 10 VDC; + 10 V ±3 %; max. 10 mA; dauerkurzschlussfest; Versorgungsspannung für ext. Geräte (z. B. Potl)
	GND	Reference ground for control interface, SELV	Bezugsmasse für Steuerschnittstelle, SELV

Motor